# Rotor Assembly 5




Figure 1

### Base Substrate 30




Figure 2




Figure 3

#### Interconnects 50




Figure 4

### Stator Coils 35




Figure 5

# Magnetic Flux Return 38




Figure 6

#### Stator Assembly 70




Figure 7

# Motor Assembly 100




Figure 8




Figure 9

Hagnetization 0-60 degrees 120-180 degrees 240-300 degrees

- Magnetization 60-120 degrees 180-240 degrees 300-360 degrees

1 Inward Leg 0-20 degrees 2 Outward Leg




Figure 10

